



A Learjet 36 ingested a mallard into an engine during the takeoff run at a northern USA airport, 4 June 2007. Pilot aborted takeoff. Cost of repairs was >\$250,000.

EXHIBIT

MORRIS #20