


Herring gull ingestion causes uncontained engine failure on MD-11 during aborted takeoff run at west coast airport in USA, 2001



Herring gull = 2.2 lbs



EXHIBIT

MORRIS #26

TABBER